



**safe lift** **TKA** 'LCD display' **TIGRIP® CRANE WEIGHERS**

Model	Product code	Measuring range tonnes	Accuracy % of nominal load	Resolution step kgs	Weight kgs
TKA 1.0	53908410	0 - 1.0	0.1	0.5	3.0
TKA 2.0	53908420	0 - 2.0	0.1	1	3.6
TKA 3.2	53908432	0 - 3.2	0.1	1	5.9
TKA 5.0	53908450	0 - 5.0	0.1	1	7.3
TKA 8.0	53908480	0 - 8.0	0.1	2	10.5
TKA 12.0	53908430	0 - 12.0	0.1	5	19.8

**Includes - crane weigher, master link, load hook, battery charger, carrying case and test certificate. The TKA is supplied with master link and load hook fitted as standard.**

The TKA crane weigher is a compact measuring device for weighing loads during lifting. Appropriate tackle can be attached to assist in the lifting and weighing. The crane weighers have a liquid crystal display (LCD), which can tare as well as show either the gross or net loads. It also indicates the overload protection at 110% of the gross weight and the status of the battery.



**safe lift** **TWF** 'LCD display' with radio remote control' **TIGRIP® CRANE WEIGHERS**

Model	Product code	Measuring range tonnes	Accuracy % of nominal load	Resolution step kgs	Weight kgs
TWF 1.0	53908416	0 - 1.0	0.1	0.5	3.0
TWF 2.0	53908417	0 - 2.0	0.1	1	3.6
TWF 3.2	53908418	0 - 3.2	0.1	1	5.9
TWF 5.0	53908419	0 - 5.0	0.1	1	7.3
TWF 8.0	53908421	0 - 8.0	0.1	2	10.5
TWF 12.0	53908433	0 - 12.0	0.1	5	19.8

**Includes - crane weigher, master link load hook, battery charger, carrying case and test certificate. The TWF is supplied with master link and load hook fitted as standard.**

The TWF has all the same features and benefits as the TKA, but in addition the TWF is provided with (cordless) radio control and RS232 interface. Readings can be take off the remote control device and transmitted to a PC

**Included in delivery of TKA**  
Crane weigher, master link, load hook, battery charger (3 V, 700 mA), carrying case and test certificate.

**Included in delivery of TWF**  
As per TKA but complete with a radio remote control.

**Optional for TWF**  
PC cable, user software.

